Name: Location:			60'-0" CATTLE BUILDING			I HIS DOCUMEN INFORMATION PRO ACCU-STEEL INC. IT	PRIETARY TO	0	OI
Email:			INTEGRITY TRUSS			REPRODUCED, USED WITHOUT PRIOR	, OR DISCLOSED	HCCII	<i>-Steel</i>
Phone:	Cell:					PERMISSION OF AC	CU-STEEL INC.	FABRIC COVER	ED BUILDINGS
Fax:	Cover: Enduro-Loc™ Keder		Notes: BEAM BOTH SIDES			Date: 08/06/2020			
Length: Centers: Arc:			STANDARD EAVE ONE SIDE			Project:		1-877-338-6936	
Rafter Coating: ASTM-A123 Hot Dip Galvanized 3.9 mils Zinc			PREMIUM EAVE ONE SIDE			Drawn By: JCB		www.asicoverbuildings.com	
Foundation:			PROFILE SUBJECT TO CHANGE			Sales #		sales@asicoverbuildings.co	
35'		+ + + + + + + + + + + + + + +		+++++++++++++++++++++++++++++++++++++++	+++++		- + + + + + + + + - - + + + + + + + + +		++++- ++++- ++++-
30 + + + + + + + + + + + + + + + + + + +	+++++++++++++++++++++++++++++++++++++++	+ + + + + + + + + + + + + + + + + + + +			+ + + + + + + + + + + + + + + + + + + +	+++++++++++++++++++++++++++++++++++++++	- + + + + + + - - + + + + + + - - + + + +	+ + + + + + + + + + + + + + + + + + +	+++++
254 + + + + + + + + + + + + + + + + + + +	+++++++++++++++++++++++++++++++++++++++	++++		+++++++++++++++++++++++++++++++++++++++	+++++		- + + + + + + - + + + + + + + + + +		+++++++++++++++++++++++++++++++++++++++
200 + + + + + + + + + + + + + + + + + +	+ + + + + + + + + + + + + + + + + + + +	+++++		+++++++++++++++++++++++++++++++++++++++	+++++	+++++++++++++++++++++++++++++++++++++++			+++++++++++++++++++++++++++++++++++++++
101		+ + + + + + + + + + + + + + + + + + + +		+++++++++++++++++++++++++++++++++++++++	+++++	+++++++++++++++++++++++++++++++++++++++			+++++++++++++++++++++++++++++++++++++++
5'+++++++++++++++++++++++++++++++++++++	4 +	+ + + + + + + + + + + + + + + + + + + +		+ + + + + + + + + + + + + + + + + + +	+ + + + + + + + + + + + + + + + + + + +	+ + + + + + + + + + + + + + + + + + +			+ + + + + + + + + + + + + + + + + + +
0	+++++++++++++++++++++++++++++++++++++++	+ + + + + + + + + + + + + + +		+++++++++++++++++++++++++++++++++++++++	+++++++++++++++++++++++++++++++++++++++	+++++++++++++++++++++++++++++++++++++++	· + + + + + + + - · · · · · · · · · · ·	+ + + + + + + + + + + + + + + + + + +	++++-
5'+++++++++++++++++++++++++++++++++++++	+ + + + + + + + + + + + + + + + + + +	+ + + + + + + + + + + + + + + + + + + +		+ + + + + + + + + + + + + + + + + + +	+ + + + + + + + + + + + + + + + + + +	+ + + + + + + + + + + + + + + + + + +	+ + + + + + + + + + + + + + + + + + +		+ + + + + + + + + + + + + + + + + + +
10'	25' 20'	+ + + + +	10' 5' 0'	5' 10'	15'	20' 25	5' 30'	35' 40	++++-
35 30	23 20		60'-0" OUTSID	E OF BEAMS-		ZU Z:	30	<i>55</i> 40	1